



CES Environmental Services Inc.

Harris County, Houston, Texas

Open House / Information Session December 11, 2014







AGENDA:

- Introduction
- Background
- Actions on Site
- Timeline
- Neighborhood Orientation Map
- Above Ground Storage Tanks
- Water Removal Map / Storm Sewers
- Preliminary Assessment
- Contact Information





Background

- CES Environmental Services filed for bankruptcy in 2010 leaving:
- Approximately 11 vacuum boxes
- 2 roll-off boxes
- 12 frac tanks
- 2 tanker trailers
- 22 above ground storage tanks (ASTs), 19 wastewater treatment tanks, waste piles, and numerous totes, vats, drums, and smaller containers were left on Site
- These contain materials including acids, corrosives, flammables, and specific hazardous wastes including benzene, cresol (phenols), lead, and chromium





Actions on Site

- The EPA's response actions on the Site began in late August 2014.
- To date, the EPA has sampled and/or received analytical results on chemical composition for almost all of the larger containers
- Removal/disposal of chemicals at the facility
- Continued actions will include the clean up and disposal of all containers and visually contaminated asphalt/concrete, soil, and debris









Getting to Green

EPA Time-Critical Removal Actions on Site: CES Environmental Service Inc.

August 14, 2014—

Superfund Division
Director gives verbal
authority of \$500,000
to begin Time-Critical
Emergency Removal
Action

September, 2014—

Preliminary
Assessment/Site
Inspection by TCEQ

October, 2014—

Removal/Disposal of debris and visible chemical spillage to surfaces and soil begins

February, 2015—

Nov. 19-21, 2014— EPA and

Public Health officials make

door-to-door visits to pass out

fact sheets and hear concerns

Our goal is to have the Site cleared of all hazardous waste materials

RED

YELLOW

GREEN

August 2014— Emergency Removal actions to address oil spill caused by vandalism. Six inches of rain carried storm water and oily material from site into sewers and residential areas. Sampling and fencing repairs conducted

October, 2014—

Removal/Disposal of chemicals in pails, drums, totes, vats, and above ground storage containers begins **December 11, 2014**— EPA holds Open House/Information Session to inform residents of removal progress and take questions





Neighborhood Orientation













Totes and drums scattered throughout the property

2 Tank Trailers: Reported as containing oily water with solids. Sampled 8/7/14




Above Ground Storage Tanks (20): mainly contaminated water and sludge; 1 tank has bulked tote/drum liquids








Water Removal and Storm Sewers



AST North Tank Farm	
AST NOTCH TAIK FAITH	
Facility ID	Bluebonnet ID
OIL 1	OT1
OIL 2	OT2
OIL 3	OT3
OIL 4	OT4
OIL 5	OT5
OIL 6	OT6
OIL 7	OT7
OIL 8	OT8
OIL 9	OT9
Oily Water	WT1
Recycled Oil	FT1



AST South Tank Farm	
Facility ID	Bluebonnet
	ID
OT 1	NP1
OT 2	NP2
OT 3	NP3
OT 4	NP4
OT 5	NP5
OT 6	NP6
OT 7	NP7
0T 8	NP8





Preliminary Assessment

- A review of Site records, permits, pathway data, target data, land titles, to establish past activities on the Site and the need for further investigation
- Will determine if the Site will qualify to be placed on the National Priority List or requires a long-term removal
- Information will be available on the EPA website and in the Site repository





Questions, Comments, Concerns

Contacts:

• Gary Moore, EPA On-Scene Coordinator

Phone: 214.665.6609 or 1.800.533.3508 (toll-free) moore.gary@epa.gov

• Bill Little, EPA Community Involvement Coordinator

Phone: 214.665.8131 or 1.800.533.3508 (toll-free) little.bill@epa.gov

• Carrie M. Bradford, Toxicologist, TX Department of Health Services

Phone: 512.776.3004 or carrie.bradford@dhs.state.tx.us